

## Instructions for Continued Airworthiness Assessment

S & T Aircraft Accessories, Inc.  
310 FM 483  
New Braunfels, Texas 78130  
FAA Repair Station Number CC2R737K  
Unlimited Accessory Class 1 & 2

This ICA Assessment is applicable to the Repair Specification ST-20210101, revision IR, dated 01 January 2021 as developed by the repair station listed therein.

After review of the Repair Specification and the manuals for each engine and aircraft as referenced in the Installation Eligibility section therein, this repair station finds no need for modified Instructions for Continued Airworthiness to be issued. Data supporting this decision is:

- The process as described in the Repair Specification for the manufacture of the bearings, indicate identity in terms of material to the original manufacturer's product as determined by chemical analysis of the original manufacturer's product.
- The process as described in the Repair Specification for the manufacture of the bearings, indicate identity in terms of dimension to the original manufacturer's product as determined by dimensional analysis of the original manufacturer's product.

No modifications to the Instructions for Continued Airworthiness are needed.

**Repair Specification Title: Procedure for Manufacturing Fuel Pump Bearings**  
**Repair Specification Number: ST-20210101**  
**Date: 01 January 2021**

**Title/Signature Page**

**Revision Number: IR**  
**Revision Date:**